


OSHA Most Frequently Cited Serious Violations

General Industry - FY-2009




OSHA Federal Standards

October 1, 2008 – September 30, 2009

Most Frequently Cited Serious Violations in General Industry FY 2009

Standard & Subpart: 1910.




Note: There were also 1400 Section 5(a)(1) General Duty Clause violations cited for all inspections during this period.

Number of Serious Violations – FY 2009



Subpart D - Walking/Working Surfaces (1910.21 - 30)

Standard: 1910.



Subpart E – Exit Routes, Emergency Action Plans, and Fire Prevention Plans (1910.33 - 39)


Standard: 1910.



Number of Serious Violations – FY 2009

Subpart F - Powered Platforms (1910.66 - 68)


Standard: 1910.



Number of Serious Violations – FY 2009

Subpart G - Occupational Health (1910.94 - 98)



Standard: 1910.



Number of Serious Violations – FY 2009


Subpart H - Hazardous Materials (1910.101 - 126)

Standard: 1910.



Number of Serious Violations – FY 2009



Subpart I - Personal Protective Equipment (1910.132 - 139)



Number of Serious Violations – FY 2009

Subpart J - General Environmental Controls (1910.141 - 147)



Standard: 1910.



Number of Serious Violations – FY 2009

Subpart K - Medical & First Aid (1910.151 - 152)


Standard: 1910.



Number of Serious Violations – FY 2009



Subpart L - Fire Protection (1910.155 - 165)

Standard: 1910.





Subpart M - Compressed Gas & Air Equipment (1910.166 - 169)

Standard: 1910.




Subpart N - Materials Handling & Storage (1910.176 - 184)



Number of Serious Violations – FY 2009

Subpart O - Machinery & Machine Guarding (1910.211 - 219)


Standard: 1910.



Number of Serious Violations – FY 2009

Subpart P - Hand & Portable Powered Tools (1910.241 - 244)


Standard: 1910.





Number of Serious Violations – FY 2009

Subpart Q - Welding, Cutting & Brazing (1910.251 - 255)

Standard: 1910.




Subpart R - Special Industries (1910.261 - 272)



Subpart S - Electrical (1910.301 - 399)




Standard: 1910.



Number of Serious Violations – FY 2009

Subpart Z - Toxic & Hazardous Substances (1910.1000 - 1450)



Number of Serious Violations – FY 2009